## EXHIBIT A TO OFFER TO PURCHASE -- CITY OF MILWAUKEE SCOPE OF WORK

3605 North 12th Street

Other  $\square$ 

**Scope of Work for Property Located at:** 

**Property is:** Single Family  $\Box$  Duplex  $\boxdot$ 

Date:	10/18/2018	_	-	□ VACANT ☑		
	Scope upon visual inspection only, overy of conditions that are or may o			or conclusions, and is not response	onsible for errors,	
	REPAIRS. All buyers m			nd ohtain "Essential	Renair Verificat	tion Form"
	same to DCD within 180					
Location	Required Work		Note/Comments		Cost	
Entire Building	Structural Violations	n/a ☐ Yes ☐			\$	<u> </u>
	Defective/Missing HVAC	n/a ☐ Yes ☐			\$	_
	Defective/Missing Plumbing	n/a Yes			\$	_
	Defective/Missing Electrical	n/a  Yes			\$	<u> </u>
	Defective/Missing Egress	n/a  Yes			\$	<u> </u>
	Defective/Missing Smoke Alarm	n/a Yes			\$	<u> </u>
	Defective/Missing CO Alarm	n/a  Yes			\$	<u> </u>
	Defective/Missing Roof (Major)	n/a  Yes			\$	<u> </u>
	Missing Window(s)	n/a    Yes			\$	_
	Missing Exterior Door(s)	n/a Yes			\$	Essential Repairs Total
	Other	n/a 🗌 Yes 🗌			\$	0.00
OTHER REP	AIRS (Exterior & Interio	r). Buyer is not	tified that the follo	wing are code violation	ons that	_
must be add	ressed and are subject	to Department	of Neighborhood	Services (DNS) enfor	cement.	
Exterior Con	dition Report					
Location	Required Work	, D V D	Note/Comments		Cost	
Site	Landscaping Change (Landwelle	n/a  Yes  n/a Yes			\$ \$	_
	Steps/Handrails Service walks				\$ 500.0	<u> </u>
		n/a ☐ Yes ☑  n/a ☐ Yes ☐			\$ 500.0	<u></u>
	Fencing				э \$	_
	Parking Retaining walls	n/a ☐ Yes ☐			\$ <b>750.</b> 0	<u> </u>
	Other	n/a ☐ Yes ☐			\$ 750.0	<u></u>
	Other				\$	<u> </u>
Garage	Other	n/a ∐ Yes ∐			φ	<u> </u>
	Singles: repair	n/a Yes			\$	<del>_</del>
	Shingles: Roof over existing	n/a Yes			\$	<u> </u>
	Shingles:Tear off & re-roof	n/a  Yes			\$	<u> </u>
	Gutters/downspouts	n/a 🗌 Yes 🗌			\$	<u> </u>
	Flashing	n/a  Yes			\$	_
	Eaves	n/a Yes			\$	_
	Siding	n/a Yes			\$	_
	Doors	n/a Yes			\$	_
	Windows	n/a Yes			\$	_
	Slab	n/a Yes			\$	_
	Paint	n/a Yes			\$	_
	Electrical	n/a Yes			\$	_
	Other	n/a 🗌 Yes 🗌		_	\$	<u></u>

## Porches

House

Roof	n/a 🗌	Yes 🗌		\$
Deck-upper	n/a 🗌	Yes 🗌	7	\$ 
Decklower	n/a 🗌	Yes 🗌	7	\$ 
Steps/handrails	n/a 🗌	Yes ✓	Missing hand/guardrails on entry steps	\$ 500.00
Ceiling	n/a 🔲	Yes 🗌	_	\$ 
Guardrails	n/a 🔲	Yes 🗌		\$
Structural	n/a 🔲	Yes 🗌		\$
Paint	n/a	✓ Yes	Gutters, eaves & rafter tails. Rear jump porch decking.	\$ 1,250.00
Other	n/a 🔲	Yes 🗌		\$
Chimney	n/a 🔲	Yes 🗌		\$
Shingles: repair	n/a 🗌	Yes 🗌		\$ 
Shingles: Roof over existing	n/a 🔲	Yes 🗌		\$ 
Shingles:Tear off & re-roof	n/a 🗌	Yes 🗌		\$ 
Gutters/downspouts	n/a 🔲	Yes 🗌		\$ 
Flashing	n/a 🗌	Yes 🗌		\$ 
Eaves	n/a 🗌	Yes 🗌		\$ 
Siding	n/a 🔲	Yes 🗌		\$ 
Storm Doors	n/a 🗌	Yes 🗌		\$ 
Prime ("main") Doors	n/a 🗌	Yes 🗌		\$ 
Storm Windows	n/a 🗌	Yes 🗌		\$ 
Prime ("main") Windows	n/a 🗌	Yes ✓		\$ 400.00
Paint	n/a 🗌	Yes ✓	Gutters, eaves & rafter tails	\$ 2,250.00
Foundation	n/a 🗌	Yes 🗌		\$ 
Electrical	n/a 🗌	Yes 🗌		\$ 
Other	n/a	Yes 🗌		\$ 
Other	n/a	Yes 🗌		\$ 
Other	n/a 🔲	Yes 🗌		\$ 
Other	n/a 🗌	Yes 🗌		\$

Exterior: Estimated Cost:\* \$
\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

5,650.00

Interior Cor	ndition Report	_			_		
	Unit: Entire unit (single family) Upper unit of duplex				Lower unit of duplex   Other		
Mechanical	Required Work						
Heating	Deneig/genless heileg	-/- <b></b>	V			Ф	
	Repair/replace boiler	n/a 📙	Yes		<u></u>	\$	
	Repair radiation	n/a 📙	Yes		=	\$	
	Repair/replace furnace	n/a 🔲	Yes		<del></del>	\$	
	Repair ductwork	n/a 🔲	Yes			\$	
	Replace thermostat	n/a 🔲	Yes			\$	
	Repair/replace grilles	n/a 🗌	Yes			\$	
Flootwicel	Tune boiler/furn. insp ht exchange	er n/a	Yes	<b>✓</b>		\$	350.00
Electrical	Repair/replace receptacles	n/a 🗌	Yes			\$	
	Repair/replace switches	n/a 🔲	Yes		=	\$	
	Repair/replace fixtures	n/a 🗌	Yes			\$	
	Install outlets and circuits	n/a 🔲	Yes		==	\$	
	Install outlets and circuits	n/a 🔲	Yes			\$	
	Install outlets and circuits	n/a 🗌	Yes			\$	
	Install outlets and circuits	n/a 🔲	Yes			\$	
	Upgrade service	n/a 🔲	Yes			\$	
	Other	n/a 🔲	Yes	<b>V</b>	Open junction boxes in basement	\$	50.00
	Other	n/a 🔲	Yes	<b>V</b>	Missing coverplates	\$	50.00
Plumbing	Repair/replace kitchen sink	n/a 🔲	Yes			\$	
	Repair/replace kitchen sink fauce	t n/a 🗌	Yes			\$	
	Repair/replace tub	n/a 🔲	Yes			\$	
	Repair/replace tub faucet	n/a 🔲	Yes			\$	
	Repair/replace toilet	n/a 🔲	Yes			\$	
	Repair/replace lavatory	n/a 🔲	Yes			\$	
	Repair/replace lavatory faucet	n/a 🔲	Yes			\$	
	Repair/replace wash tub	n/a 🗌	Yes			\$	
	Repair/replace wash tub faucet	n/a 🔲	Yes			\$	
	Unclog piping:	n/a 🗌	Yes			\$	
	Repair drain/waste/vent piping	n/a 🗌	Yes			\$	
	Repair water piping	n/a 🗌	Yes			\$	
	Repair/replace water heater	n/a 🔲	Yes			\$	
	Other	n/a 🔲	Yes			\$	
	Other	n/a 🗌	Yes			\$	

Windows							
	Replace broken glass	n/a [	Yes			\$	
	Repair or replace sash	n/a [	Yes			\$	
Doors	Repair or replace doors	n/a [	Yes	<b>V</b>		\$	400.00
	Repair or repl. locks/latches	n/a [	Yes	<b>~</b>	_	\$	25.00
Walls/Ceilings	Repair or repl. @ defective	n/a [	Yes			\$	
Paint	Repair or repl. @ defective	n/a [	Yes		_	\$	
Fire Safety							
	Install smoke/CO alarm:bsmt.	n/a [	Yes			\$	
	Install smoke/CO alarm: 1st flr.	n/a	Yes			\$	
	Install smoke/CO alarm: 2nd flr.	n/a [	Yes		_	\$	
Handrails	Repair/replace defective	n/a [	 Yes			\$	
Stairs	Repair defective	n/a [	 Yes			\$	
Floors	Repair defective	n/a [	 Yes	П		\$	
Other	ricpair defective	11/4 [	 103			Ψ	
				<b>√</b>	Remove living spaces in basement or restore boarded former egress window to proper egress condition. Permit required if restoring egress.		
		n/a	Yes		condition. I crimit required in restoring egress.	\$	750.00
		n/a [	Yes			\$	
		n/a [	Yes			\$	
	_	n/a [	Yes			\$	
					Interior: Estimated Cost:	\$	1 625 00

Interior Cor	dition Report		_		
	Unit: Entire unit (single family) Upper unit of duplex		Lower unit of duplex  Other		
Mechanical	Required Work				
Heating	Repair/replace boiler	n/a ☐ Yes ☐		\$	
	Repair radiation	n/a 🗌 Yes 🗍		\$	
	Repair/replace furnace	n/a 🗌 Yes 🗌		\$	
	Repair ductwork	n/a 🗌 Yes 🗌		\$	
	Replace thermostat	n/a 🗌 Yes 🗍		<u> </u>	
	Repair/replace grilles	n/a 🗌 Yes 🗍		\$	
	Tune boiler/furn. insp ht exchange			\$	
Electrical				-	
	Repair/replace receptacles	n/a Yes		\$	
	Repair/replace switches	n/a Yes		\$	
	Repair/replace fixtures	n/a 🗌 Yes 🗌		\$	
	Install outlets and circuits	n/a Yes 🗌		\$	
	Install outlets and circuits	n/a Yes		\$	
	Install outlets and circuits	n/a Yes		\$	
	Install outlets and circuits	n/a  Yes		\$	
	Upgrade service	n/a  Yes	<del>-</del>	\$	
	Other	n/a ☐ Yes ☑	Missing coverplates	\$	50.00
Dirmshina	Other	n/a  Yes	_	\$	
Plumbing	Repair/replace kitchen sink	n/a 🗌 Yes 🗌		\$	
	Repair/replace kitchen sink fauce	t n/a 🗌 Yes 🗌		\$	
	Repair/replace tub	n/a  Yes		\$	
	Repair/replace tub faucet	n/a 🗌 Yes 🗌		\$	
	Repair/replace toilet	n/a 🗌 Yes 🗌		\$	
	Repair/replace lavatory	n/a Yes 🗌		\$	
	Repair/replace lavatory faucet	n/a 🗌 Yes 🔲		\$	
	Repair/replace wash tub	n/a ☐ Yes ☐		\$	
	Repair/replace wash tub faucet	n/a 🗌 Yes 🗌		\$	
	Unclog piping:	n/a ☐ Yes ☐		\$	
	Repair drain/waste/vent piping	n/a 🗌 Yes 🗌		\$	
	Repair water piping	n/a Yes		\$	
	Repair/replace water heater	n/a Yes		\$	
	Other	n/a Yes		\$	
	Other	n/a Yes		\$	

					Total Exterior and Interior Cost:*	\$	7,325.00
					Interior: Estimated Cost:	\$	50.00
		n/a 🗌	Yes			\$	
		n/a [	] Yes			\$	
		n/a [	Yes			\$	
o.		n/a 🗌	Yes			\$	
Other	Repair defective	n/a [	] Yes			\$	
Floors							
Stairs	Repair defective	n/a [	] Yes			\$	
Handrails	Repair/replace defective	n/a _	] Yes	. 🗆		\$	
	Install smoke/CO alarm: 2nd flr.	n/a 🗌	Yes			\$	
	Install smoke/CO alarm: 1st flr.	n/a	] Yes			\$	
rire Salety	Install smoke/CO alarm:bsmt.	n/a 🗌	] Yes			\$	
Fire Safety	Repair or repl. @ defective	n/a _	] Yes	<u> </u>		\$	
Paint	Danair ar rank @ dafaatiya	n/o	l Vac			¢.	
wans/cennigs	Repair or repl. @ defective	n/a	] Yes			\$	
Walls/Ceilings	Repair or repl. locks/latches	n/a _	] Yes			\$	
D0013	Repair or replace doors	n/a [	] Yes	<u> </u>	7	\$	
Doors	Repair or replace sash	n/a _	] Yes			\$	
	Replace broken glass	n/a	] Yes			\$	
Windows							

Inspected by: Jeff Sporer Date: 10/18/2018

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start.

Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.